



The manufacturer
may use the mark:



Revision 3.0 June 26, 2024
Surveillance Audit Due
July 1, 2027



Certificate / Certificat Zertifikat / 合格証

MIT 1211024 C001

exida hereby confirms that the:

Linear Actuator

**Mitech Control Valve (Pty) Ltd
Johannesburg, Gauteng - RSA**

Has been assessed per the relevant requirements of:

IEC 61508 : 2010 Parts 1-2

and meets requirements providing a level of integrity to:

Systematic Capability: SC 3 (SIL 3 Capable)

Random Capability: Type A, Route 2_H Device

**PFH/PFD_{avg} and Architecture Constraints
must be verified for each application**

Safety Function:

The Linear Actuator will move to the designed safe position per the actuator design within the specified safety time.

Application Restrictions:

The unit must be properly designed into a Safety Instrumented Function per the Safety Manual requirements.



Evaluating Assessor

Certifying Assessor

MIT 1211024 C001

Systematic Capability: SC 3 (SIL 3 Capable)**Random Capability: Type A, Route 2_H Device****PFH/PFD_{avg} and Architecture Constraints
must be verified for each application****Linear Actuator****Systematic Capability :**

This product has met manufacturer design process requirements of Safety Integrity Level (SIL) 3. These are intended to achieve sufficient integrity against systematic errors of design by the manufacturer.

A Safety Instrumented Function (SIF) designed with this product must not be used at a SIL level higher than stated.

Random Capability:

The SIL limit imposed by the Architectural Constraints must be met for each element. This device meets *exida* criteria for Route 2_H.

IEC 61508 Failure Rates in FIT*

Configuration	λ_{SD}	λ_{SU}	λ_{DD}	λ_{DU}	#
Spring Return	0	121	0	186	390
Double Acting	0	0	0	244	419

* FIT = 1 failure / 10⁹ hours

SIL Verification:

The Safety Integrity Level (SIL) of an entire Safety Instrumented Function (SIF) must be verified via a calculation of PFH/PFD_{avg} considering redundant architectures, proof test interval, proof test effectiveness, any automatic diagnostics, average repair time and the specific failure rates of all products included in the SIF. Each element must be checked to assure compliance with minimum hardware fault tolerance (HFT) requirements.

The following documents are a mandatory part of certification:

Assessment Report: MIT 12-11-024 R004 V1 R4 (or later)

Safety Manual: SHEQSIL-1 Rev 2



80 N Main St
Sellersville, PA 18960